

# List of RSC tools with “no training” designation for stage 3

## Fabrication tools

Gold Ball Bonder	Stage 4
Electronic Measurement, Lakeshore	Stage 4
Ellipsometer	Stage 4
Dicing Saws, ADT	Stage 4
PVD e-beam	Stage 4
FEI NOVANanoSEM 430	Stage 4
Horiba Aramis uRaman	Stage 4
Heidelberg DWL-66	Stage 4
Cambridge ALD	Stage 4
Bruker Optical Profilometer	Stage 4
SemiCorp 3150 Wafer Mounter	Stage 4

## Characterization tools

AES PHI 660	Stage 4
AFM 3100	Stage 4
Autosorb	Stage 4
Electrokinetic Analyzer	Stage 4
EPMA Cameca SX-Five	Stage 4
FIB, Scios P-FIB	Stage 4
HORIBA ARAMIS URAMAN	Stage 4
Porosimeter	Stage 4
SEM FEI NANO 430	Stage 4
SEM Hitachi S3000	Stage 4
TEM, Talos F200i	Stage 4
XPS Ulvac PHI XPS	Stage 4
X'Pert MRD	Stage 4
X'Pert MPD	Stage 4
TEM FEI Tecnai F20	Stage 4
FIB FEI Nanolab 600 Helios	Stage 4